

---

## Ground Surface Subsidence Assessment and Rehabilitation

---



Silidor Mine, Rouyn Noranda: for Newmont Mining Corp.



Moneta Mine, Timmins: for MNDM



Hollinger Mine, Timmins: for MNDM and Kinross Gold Corp.



Verglas Mine, Rouyn Noranda: for Noranda Technology Centre



175 Orebody: for Inco Mines Research  
Inco Ontario Division Mines: for Inco Limited \*



Kassandra Mines, Greece: for TVX Gold Incorporated \*



Magnesite Mines, Slovakia: for Ministry of the Environment, Slovakia \*

---

## Rock Support Design

---



Review of MWM's Langford Bolts: for Canadian Mining Industry Research Organization



Shotcrete Capacity Assessment and Review: for Inco Mines Research  
Intersection Support Demand Assessment Guidelines: for Inco Mines Research



Cablebolt Audit: for Brunswick Mining and Smelting, Noranda Incorporated



\* While employed by Klohn-Crippen Consultants Limited, Mining Group, Sudbury, Ontario